

**Subject:** RE: John's Auto Body Site BOTW 02-32-548919  
**Date:** Monday, October 18, 2021 at 9:34:37 AM Central Daylight Time  
**From:** Sykora, Candace A - DNR  
**To:** Vicki Markussen  
**Attachments:** image001.gif, image004.jpg, image005.gif, image006.gif, image007.gif, image009.gif, image010.gif, image011.gif, image003.png

Ms. Markussen,  
Groundwater samples were collected from John's Auto Body. No monitoring wells were installed. Groundwater can be collected for sampling through the installation of Geoprobes as indicated on the map. John's Auto was notified via letter of contamination at his property dated April 16, 2007. That letter can be located on page 18 of the [023548919\\_Site\\_File\\_1999\\_thru\\_2019.pdf](#)  
The PDF can be viewed online through or BRRTS On The Web that I sent you a link to previously.

I do highly recommend hiring/ consulting with an environmental professional to assist with the interpretation of the historical data identified at the site to better understand the historic and current conditions that require further attention. This site does have a long history and several impacted media that need additional evaluation.

Lastly, the data collected in 2007 and prior to may not be reflective of current conditions at the site.

Thank you for your inquiry,

Candace Sykora  
Hydrogeologist  
Remediation & Redevelopment  
Wisconsin Department of Natural Resources  
890 Spruce St, Baldwin, WI 54002  
Phone: 715-928-0452  
[Candace.sykora@wisconsin.gov](mailto:Candace.sykora@wisconsin.gov)



---

**From:** Vicki Markussen <[vicki@engagegreaterlacrosse.org](mailto:vicki@engagegreaterlacrosse.org)>  
**Sent:** Friday, October 15, 2021 12:48 PM  
**To:** Sykora, Candace A - DNR <[Candace.Sykora@wisconsin.gov](mailto:Candace.Sykora@wisconsin.gov)>  
**Subject:** RE: John's Auto Body Site BOTW 02-32-548919

**CAUTION:** This email originated from outside the organization.  
Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you so much, Candace. I only partially got through the 160 page Superfund report for John's Auto. I will circle back, but I did find this in the report for Central States Warehouse on page 16 of the 2009-02-19 Continuing Obligation(s) Applied name document. It shows four geoprobes on John's Auto. Also, those documents show John's Auto in the "Groundwater Isocontour,". I don't see a monitoring well on John's property. I only saw notifications of water contamination to Best Western and the trailer park. Am I understanding that John's was not monitored or notified of the groundwater contamination?